

FIGURE 1

**Erosion
Damage**



Leading Edge View

Prior Art

Figure 2




Figure 3




Figure 4




Figure 5

BEST AVAILABLE COPY



Figure 6




Figure 7




Figure 8

BEST AVAILABLE COPY

Average Erosion Depth
@ 10 min, 750ft/sec




Figure 9